


Gateway Safety, Inc.
4722 Spring Road, Cleveland, Ohio 44131
800-822-5347



These respirators are approved only in the following configurations:

TC-	Protection ¹	Respirators	Cautions and Limitations ²
84A-4007	N95	80105A	ABCJMNOP

1. Protection

N-95 Particulate filter (95% filter efficiency level) effective against particulate aerosols free of oil; time use restrictions may apply.

2. Cautions and Limitations

A - Not for use in atmospheres containing less than 19.5% oxygen.
B - Not for use in atmospheres immediately dangerous to life or health.
C - Do not exceed maximum use concentrations established by regulatory standards.
J - Failure to properly use and maintain this product could result in injury or death.
M - All approved respirators shall be selected, fitted, used and maintained in accordance with MSHA, OSHA and other applicable regulations.
N - Never substitute, modify, add or omit parts. Use only exact replacement parts in the configuration as specified by the manufacturer.
O - Refer to user's instructions and/or maintenance manuals for information on use and maintenance of these respirators.
P - NIOSH does not evaluate respirators for use as surgical masks.

USE RESTRICTIONS

DO NOT USE in spray painting or sandblasting operations.

DO NOT USE for protection in asbestos environments.

DO NOT USE for protection against oil based aerosols.

USE AGAINST solid and liquid non-oil particulate aerosols and relief from nuisance level odors, organic vapors (OV) and acid gases (AG), such as hydrogen fluoride and chlorine, below permissible exposure limits (PEL).

USE RESTRICTIONS

DO NOT USE in spray painting or sandblasting operations.

DO NOT USE for protections in asbestos environments.

DO NOT USE for protection against oil based aerosols.

USE AGAINST non-oil particulate aerosols, such as coal, iron ore, cotton, flour, and relief from nuisance level odors, organic vapors (OV) and acid gases (AG), such as hydrogen fluoride and chlorine, below permissible exposure limits (PEL).

USE RESTRICTIONS

DO NOT USE in spray painting or sandblasting operations.

DO NOT USE for protections in asbestos environments.

DO NOT USE for protection against oil based aerosols.

USE AGAINST non-oil particulate aerosols, such as coal, iron ore, cotton, flour, and relief from nuisance level odors, organic vapors (OV) and acid gases (AG), such as hydrogen fluoride and chlorine, below permissible exposure limits (PEL).


GATEWAY SAFETY INC.
4722 SPRING ROAD • CLEVELAND, OH 44131 • PHONE: 800-822-5347 • FAX: 216-749-0526
WWW.GATEWAYSAFETY.COM



FormFit™ AG
Particulate Respirator

Part No. 80105A

NIOSH APPROVED



- Acid Gases and Organic Vapor Relief
- Contoured Nose Cushion
- Adjustable Buckle
- Latex Free Headstrap



N95
NIOSH APPROVED

FormFit™ AG
Particulate Respirator


Box of 20
Part No. 80105A

42CFR84 Approved Product



6 62302 80105 4 3

MADE IN CHINA



- FITTING INSTRUCTIONS**
1. Hold mask in one hand over mouth and nose with straps around back of hand. Pull lower strap over head and fit around neck. Pull upper strap over head and place it above ears.
 2. To obtain a positive facial seal, adjust tension of straps. To increase tension, hold buckle and pull loose strap at either side of buckle. Tension may be decreased by holding main strap on side of buckle and pulling-out on buckle.
 3. It is the wearer's responsibility to obtain a proper fit. Each time respirator is used, wearer must test fit by cupping both hands over the respirator and exhaling vigorously. If air is felt flowing around nose or leaking around edges, wearer must reposition the respirator and/or adjust the straps until air is no longer felt flowing around the nose or leaking around the edges when wearer exhales.
 4. DO NOT enter contaminated area if a proper fit is not obtained.

- FITTING INSTRUCTIONS**
1. Hold mask in one hand over mouth and nose with straps around back of hand. Pull lower strap over head and fit around neck. Pull upper strap over head and place it above ears.
 2. To obtain a positive facial seal, adjust tension of straps. To increase tension, hold buckle and pull loose strap at either side of buckle. Tension may be decreased by holding main strap on side of buckle and pulling-out on buckle.
 3. It is the wearer's responsibility to obtain a proper fit. Each time respirator is used, wearer must test fit by cupping both hands over the respirator and exhaling vigorously. If air is felt flowing around nose or leaking around edges, wearer must reposition the respirator and/or adjust the straps until air is no longer felt flowing around the nose or leaking around the edges when wearer exhales.
 4. DO NOT enter contaminated area if a proper fit is not obtained.

- FITTING INSTRUCTIONS**
1. Hold mask in one hand over mouth and nose with straps around back of hand. Pull lower strap over head and fit around neck. Pull upper strap over head and place it above ears.
 2. To obtain a positive facial seal, adjust tension of straps. To increase tension, hold buckle and pull loose strap at either side of buckle. Tension may be decreased by holding main strap on side of buckle and pulling-out on buckle.
 3. It is the wearer's responsibility to obtain a proper fit. Each time respirator is used, wearer must test fit by cupping both hands over the respirator and exhaling vigorously. If air is felt flowing around nose or leaking around edges, wearer must reposition the respirator and/or adjust the straps until air is no longer felt flowing around the nose or leaking around the edges when wearer exhales.
 4. DO NOT enter contaminated area if a proper fit is not obtained.



LIMITED WARRANTY – Manufacturer expressly limits its warranty for this product to the physical standard and specifications set forth on this package. This limited warranty is in lieu of all other warranties, expressed or implied, including, but not limited to merchantability and fitness for particular purposes. It is the responsibility of user to determine the suitability of the product for its intended use based on the physical standard and specifications set forth hereon, and to assume all the risks and liability in connection therewith.

13.3 x 28 x 13.3